CITY OF BALTIMORE WET WI SMOKE AND DYED WA	Page 1 of 4			
Sewershed: Low Level Subsewershed: 41				
Test Type: Smoke	Ground Condition: Dry: <b>X</b> Damp: _ Wet: _	Supervisor: E.R. Crew: 4		
Manhole ID: S13G1_011MH				
	numbers, blower placement location, sandbages and locations, defect locations and photogr	g or isolation locations, street names, building raph numbers)		
502_OB01-01 BLOWE \$13G1_		SANDBAG 012		

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM						Page 2 of 4		
S	ewershed: Low Level Subsewershed: 41  Company: REI/Drayco					Date: 07/28/2008		
	Test Type: Smoke	Ground Condition: Dry: <b>X</b> Damp:_ Wet:_			Sup	Supervisor: E.R. Crew: 4		
Mar	Manhole ID: S13G1_011MH			Test ID: 1029-502			Notifications Made:X_ Resident, Fire, 311	
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)								
Defect No.	Address	Source Type	Location	Sector	Draina Area		Photo Number	
1	ATCO AVE. AT WASHINGTON BLVD.	12	06	01	100	02	1029-502_OB01-01.JPG	
2	3010 WASHINGTON BLVD	0. 18	07	02	35	03	1029-502_OB02-01.JPG	
			BSERVAT	ION COL	DES			
	Source Type Location Sector Severity							
	ain Sewer 10 MH Frame		Conc. 10			1 Public	01 No Smoke	
	rvice Line 11 Storm Drain	02 Asphalt		Field/Wo	ods 0	2 Private	02 Trace	
	eanout 12 Catch Basin	03 Paved 0		Alley Golf Cou	ırsa		03 Moderate 04 Major	
					1126		UH   IVIAJUI	
	yy. Drain 15 Excavation	06 Curb	17	31101	$-\parallel$			
07 Sta	air. Drain 16 Water Line	07 Yard - F						
	und. Drai 17 Tele. Pole	08 Yard - E						
09 Blo	dg. Interio 18 Other	09 Yard - S	side					

PAGE 3 OF 4

## CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 502 Date: 07/28/2008 Basin: LL - 41 Manhole ID: S13G1\_011MH Defect No: OB01 Supervisor: E.R. Crew: 4 Dye Test Recommended: N

Address: ATCO AVE. AT WASHINGTON BLVD.

Source Type: 12 Catch Basin Location: 06 Curb

Sector: 01 Public Severity: 03 Moderate Drainage Area: 100

Comments: SMOKE COMING FROM CATCH BASIN AT ATCO AVE. AND WASHINGTON BLVD.

## SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 1029-502\_OB01-01.jpg

## CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 502 Date: 07/28/2008 Basin: LL - 41 Manhole ID: S13G1\_011MH Defect No: OB02 Supervisor: E.R. Crew: 4 Dye Test Recommended: N

Address: 3010 WASHINGTON BLVD.

Source Type: 18 Other Location: 07 Yard - Front

Sector: 02 Private Severity: 03 Moderate Drainage Area: 35

Comments: SMOKE COMING FROM THIS STRUCTURE AT 3010 WASHINGTON BLVD.

## SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-01 Filename: 1029-502\_OB02-01.jpg